			-,	ouisville		iviotor, v		ac iviotors i	-,	, , ,	,ust 24 2010
Bldg	Location	Туре	HP	RPM	Volts	Ph	Mfr	Model #	Pump Notes	Job Description	Construction Description
1	10th Fl Mech Rm	Ex Fan 2A	1.5	1735	230-460	3	Marathon	XVL145TTDR- 532GAA	Runs 24 hrs/day	Needs EE motor	Exhaust Fan 2A-No construction issues anticipated Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
	IVIECTI IVIII	EX Fall ZA	1.5	1735	230-460	3	Maratrion	0020/01	rano 2 i morady	110000 EE motor	clevator) indicate ne lesace at time time.
1	10th Fl Mech Rm	Ex Fan 4A	3	1745	230-460	3	Century	R206	Runs 24 hrs/day	Needs EE motor	Exhaust Fan 4A-No construction issues anticipated Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time. No construction issues anticipated. Room space,
1	5th Fir Roof 2	Heat Recovery	1	1725	200	3	Emerson	P63CZ0-3021	Pump-TACO, 6.15 impellor	Needs EE motor	room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	7th FL Mechanic al RoomA- 771	HW	0.75	1725	230-460	3	Emerson	P63CKA-2740	Pump-TACO, 6.35 impellor	Needs EE motor	No construction issues anticipated. Room space, room access, and floor access (via freight elevator) indicate no issues at this time.
1	7th FL Mechanic al RoomA- 771	HW	0.75	1725	230-460	3	Emerson	P63CKA-2740	Pump-TACO #1641C3N3	Needs EE motor	No construction issues anticipated. Room space, room access, and floor access (via freight elevator) indicate no issues at this time.
1	7th FL Mechanic al RoomA- 771	HW	1	1725	230-460	3	Emerson	??		Needs EE motor	No construction issues anticipated. Room space, room access, and floor access (via freight elevator) indicate no issues at this time.
1	7th FL Mechanic al RoomA- 771	Heat Recovery	1.1	1725	230-460	3	Emerson	P63CJ2-2739	Pump-TACO #1641C3N3	Needs EE motor	Standard size doorway and floor access (via freight elevator), yet this motor is in a hard-to-access area above ductwork. A ladder will be needed
1	7th FL Mechanic al RoomA- 771	Heat Recovery	1.1	1725	230-460	3	Emerson	P63CJ2-2739	Pump-TACO, 6.35 impellor	Needs EE motor	A ladder will be neededRoom space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time. No construction issues anticipated. Room space,
1	<u>C-220</u>	Heat Recovery	2	1745	230-460	3	Century	E102	Pump-TACO, 9.67	Needs EE motor	room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	<u>C-220</u>	HW	3	1745	230-460	3	Century	6-355641-01	Pump-TACO, 7.7	Needs EE motor	A ladder will be neededRoom space, room access (standard size doorway), and floor access (via freight elevator) indicate no issues at this time.
1	<u>C-220</u>	HW	3	1745	230-460	3	Century	6-355641-01	Pump-TACO, 7.7	Needs EE motor	A ladder will be neededRoom space, room access (standard size doorway), and floor access (via freight elevator) indicate no issues at this time. No construction issues anticipated. Room space,
1	D-Wing mech	HW	3	1725	230-460	3	Baldor	M32IIT	Pump-TACO, FE1508E2D1E2 L0	Needs EE motor	room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	D-Wing mech	HW	3	1725	230-460	3	Baldor	M32IIT	Pump-TACO, FE1508E2D1E2 L0	Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	M-003 Main Bsmt MER	HW	2	1745	230-460	3	Century	E102	Pump-TACO, FM1508B2	Needs EE motor	Mechanical Room is on Ground Level. No construction issues anticipated. Room space, room access indicate no issues at this time.
1	M-003 Main Bsmt MER	HW	2	1745	230-460	3	Century	E102	Pump-TACO, FM1508B2	Needs EE motor	Mechanical Room is on Ground Level. No construction issues anticipated. Room space, room access indicate no issues at this time.
1	<u>M-503</u>	HW	1.5	1735	230-460	3	Marathon	9VJ145TTDR58 70AA	Pump-TACO, 7.9 impellor	Needs EE motor	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	<u>M-503</u>	HW	1.5	1735	230-460	3	Marathon	9VJ145TTDR58 70AA		Needs EE motor	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	M-503	HW	2	1735	230-460	3	Marathon	9VJ145TTDR58 70AA		Needs EE motor	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
								9VJ145TTDR58			No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no
1	<u>M-503</u>	HW	2	1735	230-460	3	Marathon	70AA 9VK145TTER58		Needs EE motor	issues at this time. No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no
1 Bldg	M-503 Location	HR Type	2 HP	1735 RPM	230-460 Volts	3 Ph	Marathon Mfr	71AA Model#	Pump Notes	Needs EE motor Job Description	issues at this time. Construction Description
Diug											

ı	I	1 1	Ī	I	1	l i	1	I	ı	1	1
1	10th Fl Mech Rm	Ex Fan 1A	5	1725	230-460	3	Reliant	P18G312L	Runs 24 hrs/day	Needs EE motor	Exhaust Fan 1A-No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	5th Fir Roof	CHW	7.5	1755	230-460	3	Baldor	M33IIT	Pump-TACO #FE2508E2FIF2	Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
	5th Fir Roof							M33IIT	Pump-TACO #FE2508E2FIF2 L0	Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
7	Basement	CHW	7.5	1755 3470	230-460	3	Baldor Marathon	2VA184TTDR76 04DT	LU	Needs EE motor & VSD	There is room and doorway spaceInstaller must keep in mind that there is one stainwell and no freight elevator, however.
7	Basement	HW	7.5	3470	230-460	3	Marathon	2VA184TTDR76 04DT		Needs EE motor & VSD	There is room and doorway spaceInstaller must keep in mind that there is one stairwell and no freight elevator, however.
7	Basement	HW	7.5	3470	230-460	3	Marathon	2VA184TTDR76 04DT		Needs EE motor & VSD	There is room and doorway spaceInstaller must keep in mind that there is one stainwell and no freight elevator, however.
21	Chiller Plant	Cooling tower pump	50	1770	230-460	3	Baldor	M2543T		Needs VSD	The weight of this motor may be too heavy for just 1-2 installers to move by handassistance may be needed. Room space, room access (standard size doorways) and floor access indicate no issues at this time.
21	Chiller Plant	Cooling tower pump	50	1770	230-460	3	Baldor	M2543T		Needs VSD	The weight of this motor may be too heavy for just 1-2 installers to move by handassistance may be needed. Room space, room access (standard size doorways) and floor access indicate no issues at this time.
21			30	1770	230-400	3	Baldoi				No construction issues anticipated. Room space, room access (standard size doorway or outside
1	D-Wing Main MER	CHW	5	1725	230-460	3	Baldor	M32I8T	Pump-TACO, FE2508E2FIF2L 0	Needs EE motor & VSD	access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time. No construction issues anticipated. Room space,
1	D-Wing Main MER	CHW	5	1725	230-460	3	Baldor	M32I8T	Pump-TACO, FE2508E2FIF2L 0	Needs EE motor & VSD	room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
	M-003 Main							0.055000.04	Pump-TACO,		Mechanical Room is on Ground Level. No construction issues anticipated. Room space, room
1	Bsmt MER	CHW	7.5	1755	230-460	3	Century	6-355802-01	FM3007B2	VSD	access indicate no issues at this time.
1	M-003 Main Bsmt MER	CHW	7.5	1755	230-460	3	Century	6-355802-01	Pump-TACO, FM3007B2	Needs EE motor & VSD	Mechanical Room is on Ground Level. No construction issues anticipated. Room space, room access indicate no issues at this time.
1	M-003 Main Bsmt MER	CHW	15	1755	230-460	3	Century	6-357216-01	Pump-TACO, FM4008B2	Needs EE motor & VSD	Mechanical Room is on Ground Level. No construction issues anticipated. Room space, room access indicate no issues at this time.
1	M-003 Main Bsmt MER	CHW	15	1755	230-460	3	Century	6-357216-01	Pump-TACO, FM4008B2	Needs EE motor	Mechanical Room is on Ground Level. No construction issues anticipated. Room space, room access indicate no issues at this time.
1	<u>M-501</u>	HW	5	1740	230-460	3	Baldor	VJMM3218T	Pump-TACO, V3009AE2JCB6 84M	Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	<u>M-501</u>	HW	5	1740	230-460	3	Baldor	VJMM3218T		Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	<u>M-501</u>	CHW	7.5	1725	230-460	3	Baldor	JMM3311T		Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	<u>M-501</u>	CHW	7.5	1725	230-460	3	Baldor	JMM3311T	Pump-TACO, 7.9 impellor	Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	<u>M-503</u>	CHW	7.5	1765	230-460	3	Emerson	AD79A		Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	<u>M-503</u>	CHW	7.5	1765	230-460	3	Emerson	AD79A		Needs EE motor & VSD	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time.
1	SB-4	Domestic Cold Water	15	3480	230-460	3	US Electronic Motors	Unimount 125	Pump-SYNCRO FLO-6M-15	Needs EE motor	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time. (see photo in Additional Info doc.)
	SB-4	Domestic Cold Water						Unimount 125	Pump-SYNCRO FLO-6M-15	Needs EE motor	No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time. (see photo in Additional Info doc.)
1		Domestic	15	3480	230-460	3	US Electronic Motors		Pump-SYNCRO		No construction issues anticipated. Room space, room access (standard size doorway or outside access through oversize wall louvers/windows), and floor access (via freight elevator) indicate no issues at this time. (see photo in Additional Info
1	SB-4	Cold Water	15	3480	230-460	3	US Electronic Motors	Unimount 125	FLO-6M-15	Needs EE motor	doc.)